

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1861	DATE	July 13. 2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	At the torsional damper, which connects the motor and power transmission, screws connecting torsional damper and engine are not tighten properly in some units. Accordingly, keeping operation as it is may break the screws or let them fall off ,and disable the unit to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	JD-6330 JD-6830	2010	6
TOTAL			6