

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2970	DATE	JULY 13.2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some delivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-30K	CT226	2011	1
	CT230	2011	3
EDM-45K	CT401	2011	4
KDN-65K	CT652	2011	2
—	EG220	2011	71
	EG222	2011~2012	67
	EG224	2011	96
	EG224X	2011	99
EDM-30J	EG227	2011	40
	EG227X	2011	48
	EG230	2011	18
	EG230X	2011	30
EDM-34L	EG326Y	2011	12
	EG328Y	2011	28
EDM-34L	EG330Y	2011	56
	EG334Y	2011	102
EDM-45L	EG437Y	2011	38
	EG441Y	2011	23
	EG445Y	2011	42
KDN-53L	EG453Y	2011	33
—	EG48	2011	7
	EG53	2011	42
—	EG53Y	2011	10
KDN-65H	EG58	2011	3
	EG65	2011	9
—	JD-1630	2011	2
KDN-65J	EG58Y	2011	3
	EG65Y	2011	9
—	EG76	2011	1
—	EG76Y	2011	1
	EG83Y	2011	8

EDM-C34D	AE330	2011	42
	AE334	2011	5
EDM-C39	AE439	2011	38
EDM-C45F	AE445	2011	34
—	AG460	2011	16
—	AG470	2011	17
—	AG572	2011	25
—	GC585	2011	7
		Total	1092