

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2977	DATE	Jul. 19, 2012
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>On vehicles with which optional accessory auto-light is equipped, illumination of the instrument panel meters in the passenger compartment will not turn on during operation of the auto-light.</p> <p>The problem is caused by improper adjustment of electrical circuits between auto-light and body side.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJ2	IMPREZA	2011~2012	6
DBA-GJ3		2011~2012	6
DBA-GP2		2011~2012	17
DBA-GP3		2011~2012	5
		TOTAL	34