

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2978	DATE	July. 19. 2012
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>With regard to the inside door handle and the door latch of the driver's door, the notch for mounting the cable connecting them may be provided in an improper position, and the cable may, if the inside door handle is operated to open the door and the door lock is operated at the same time, sag and the cable end can get on the notch. Should this happen, the door would not be latched securely and could open unintentionally when the auto door lock is actuated or the door lock is manually operated immediately after the vehicle started to move.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RM1	CR-V	2011~2012	6,086
DBA-RM4		2011~2012	4,145
		TOTAL	10,231