

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2998	DATE	July 23, 2012
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some deliivry guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-5SDK5	TOYOTA JOBSUN	2011	8
EDM-5SDK6		2011	8
TOTAL			16