

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2999	DATE	July 24, 2012
MANUFACTURER	HOWA MACHINERY,LTD.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some deliivry guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-JV40CW6	JV40CW	2011	1
TOTAL			1