

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	No. 3000	DATE	July. 24. 2012
MANUFACTURER	Niigata transys co.,ltd		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some deliivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-NR2A	NR42	2012	7
TOTAL			7