

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2974	DATE	July 26,2012.
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. , LTD.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some deliivry guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
L2DA	V2-3B	2011	6
EDM-V36	V3-6	2011	59
EDM-V46	V4-6	2011	20
EDM-V51	V5-1	2011	4
EDM-RW05	LK40Z-5	2011	13
EDM-RX05	LK50Z-5	2011	3
WA117	WA20-6	2012	4
			TOTAL
			109