VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	3 0 0 4	DATE	July 30 , 2012		
MANUFACTURER	NIPPON YUSOKI C 0 .,LTD.				
DESCRIPTION OF	In the electric power-steering of the forklift truck, due to an improper				
DEFECT	program of the controller, overcurrent will be caused in the				
	power-steering motor at the time of steering operation.				
	Therefore, the error message would be displayed on the operation screen,				
	and the function of power-steering would not work.				

ТҮРЕ	COMMERCIAL NAME	MOI YE		NUMBER OF VEHICLES
		RECA	LLED	
NICHIYU 241AC	TRANSER	2 0	1 1	3 4
NICHIYU ZAF-241C		2011/2012		2 5
NICHIYU 251AC				2
			TOTAL	6 1