VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

	Domestic Import Vehicles				
CAMPAIGN No.	3026	DATE	24 September 2012		
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO., LTD.				
DESCRIPTION OF DEFECT	Because of the improper fixing of the cable at the forward/reverse switching lever system, the outer frame of the cable might be damaged by the repeated force at the clamping point during the steering operation. Therefore the cable might not be operated properly and the vehicle might travel by the steering operation even if the forward/reverse lever is at the neutral position.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
_	CC135C-3	2006-2007	47	
_	HW30∨WH	2006-2007	11	
_	CC150C-3	2006-2007	44	
_	HW41∨WH	2006-2007	12	
_	CC135C-3A	2007-2010	196	
_	HW30VWH−2	2007-2010	27	
_	CC150C-3A	2007-2010	209	
_	HW41VWH-2	2007-2010	35	
_	ZC35C	2010	52	
_	ZC50C	2010	46	
_	HW41VWH−3	2010	5	
_	CC135-3	2006-2007	4	
_	CC150-3	2006	1	
_	HW41VSH	2006	1	
_	CC135-3A	2007-2010	8	
_	CC150-3A	2007-2010	10	
	HW41VSH-2	2007	1	
	ZC35T	2010	7	
	ZC50T	2010	2	
		TOTAL	718	