

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3025	DATE	September 7, 2012
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>On left rear door, in some vehicles, the resin parts in the door latches were broken, due to manufacturing failure. In this case, the left rear door may not be closed, as door lock will not work correctly.</p> <p>In the worst case, there is a possibility to open the left rear door during vehicle driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MH34S	WAGON R	2012	2,476
		TOTAL	2,476