

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3010	DATE	Aug. 2 2012
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large- and medium-sized buses, the material of the exhaust pipe (center pipe) is improper. The portion around the welding point at the bottom center of the center pipe may corrode due to the water condensed in the pipe, which may result in pitting. If the vehicle continues to be used in this condition, exhaust gas leakage from the exhaust pipe may result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-MP35FK	FUSO AERO STAR	2010~2012	31
LKG-MP35FM		2010~2012	245
LKG-MP35FP		2010~2012	81
LKG-MP37FK		2010~2012	432
LKG-MP37FM		2010~2012	93
QKG-MP35FK		2012~2012	6
QKG-MP35FM		2012~2012	42
QKG-MP35FP		2012~2012	30
QKG-MP37FK		2012~2012	9
QKG-MP37FM		2012~2012	11
LDG-MM96FH		FUSO AERO ACE	2011~2012
SDG-MM96FH	2011~2012		28
TDG-MM96FH	2012~2012		21
SKG-MK27FH	FUSO AERO MIDI	2011~2012	16
TKG-MK27FH		2012~2012	13
LKG-AP35FK	—	2011~2011	2
LKG-AP35FM		2010~2011	20
LKG-AP35FP		2010~2011	3
LKG-AP37FK		2010~2011	24
LKG-AP37FM		2010~2010	5
		TOTAL	1,119