

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3012	DATE	August 30 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>This problem is with the nut used with a mating bolt to fix the seat belt anchor, located above the driver's seat of the route buses. Since the anchor nut is not proper, the anchor bolt had to be forcefully screwed into the nut, and as the result, the threads on the bolt were stripped. If use of the seat belt is continued under this condition, the bolt may become loose and the seat belt may fall off from the anchor.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-LV234L3 LKG-LV234L3 OPG-LV234L3	ERGA	2012	15
LDG-LV234N3 LKG-LV234N3		2012	14
LDG-LV234Q3 LKG-LV234Q3 OPG-LV234Q3		2012	12
SDG-LR290J1	ERGA MIO	2012	21
		TOTAL	62