

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3013	DATE	August 30 ,2012
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	This problem is with the nut used with a mating bolt to fix the seat belt anchor, located above the driver's seat of the route buses. Since the anchor nut is not proper, the anchor bolt had to be forcefully screwed into the nut, and as the result, the threads on the bolt were stripped. If use of the seat belt is continued under this condition, the bolt may become loose and the seat belt may fall off from the anchor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-KV234L3	HINO Blue Ribbon II	2012	3
LKG-KV234N3 LKG-KV234N3KAI		2012	9
LKG-KV234Q3 LKG-KV234Q3KAI		2012	4
SDG-KR290J1 SDG-KR290J1KAI	HINO Rainbow II	2012	25
		TOTAL	41