## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1878	DATE	Nov 21, 2012	
MANUFACTURE	Harley-Davidson Motor Company			
	(Japanese Importer : Harley-Davidson Japan K.K. )			
DESCRIPTION OF	The License Plate Bracket Assembly (P/N 67900032 Dom and 67900033 HDI) installed on these			
DEFECT	vehicles may lose retention to the rear fender. This condition may lead to contact with the rear tire which			
	could cause the License Plate Bracket to rotate, possibly damaging the rear brake line. If this condition			
	remains undetected, it may affect rear brake performance, increasing the risk of a crash, which could lead			
	to injury or death of the rider. Har	ley-Davidson has initiated this reca	ll to correct this condition.	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ННН	VRSCDX	2011–2012	240
		TOTAL	240