## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3060	DATE	Nov.15.2012
MANUFACTURER	NISSAN		
DESCRIPTION OF DEFECT	On some engines, the fuel pipe caused duraddition to this, there the flare nut which serepeated high injection from the wrinkle, which	ing the manufacturi e are cases that the cures the fuel pipe n pressure is applic	tightening torque of is low. Therefore, if ed, a crack may occur

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
PA-AHW41	CIVILIAN	2004	1, 647
PA-AVW41		2007	801
PA-AJW41		2001	381
PA-ACW41			41
		TOTAL	2,870