

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3057	DATE	Nov.13.2012
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty sight seeing buses, among the brackets which are fixing the oil reservoir tank for the hydraulic fan drive, due to incorrect manufacture of the lower bracket with the material of thin board thickness, the upper bracket may be cracked by the vibration during driving. If the vehicle is operated under the condition continuously, the lower bracket and the oil reservoir tank may be cracked, in the worst case, there is a possibility that the tank may come off the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU1ESAA	HINO SELEGA	2005~2007	4
PKG-RU1ESAA			
LKG-RU1ESBA		2012	178
LKG-RU1ESBAKAI			
QPG-RU1ESBA			
QPG-RU1ESBAKAI			
LJG-RU1ASBR		2012	1
ADG-RU8JHAA		2006	1
LDG-RU8JHBA		2012	20
SDG-RU8JHBA			
		TOTAL	204