

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3058	DATE	November 13 ,2012
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	On certain heavy duty sight seeing buses, among the brackets which are fixing the oil reservoir tank for the hydraulic fan drive, due to incorrect manufacture of the lower bracket with the material of thin board thickness, the upper bracket may be cracked by the vibration during driving. If the vehicle is operated under the condition continuously, the lower bracket and the oil reservoir tank may be cracked, in the worst case, there is a possibility that the tank may come off the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-RU1ESAJ	ISUZU GALA	2006-2008	3
LKG-RU1ESBJ		2012	130
OPG-RU1ESBJ			
BDG-RU8JHAJ		2008	1
SDG-RU8JHBJ		2012	8
		TOTAL	142