

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3043	DATE	October 25 ,2012
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	A wrong service part, i.e., a band with wrong specifications was supplied, for fixing a fuel tank to a tractor equipped with an air-suspension system. When a vehicle using this wrong type of band runs on a rough road, the fuel tank may rattle and move with repeated impact from vibration. Thus, if these vehicles are continuously used, the fuel tanks will rub against the fuel filter bracket metal fittings and be damaged. In the worst case, fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KC-EXD50G2	GIGA	1998-1999	4
KC-EXD50L2		1997-2000	11
KL-EXD51D3		2003-2005	21
PJ-EXD51D6		2005	1
KL-EXD51G3		2003-2005	73
PJ-EXD51G6		2005-2006	47
KL-EXD51L3		2003-2005	20
PJ-EXD51L6		2005-2006	14
KC-EXD52D2		1997-2000	141
KL-EXD52D3		2003-2005	1,422
PJ-EXD52D6		2005-2006	859
KC-EXD52E2		1997-2000	48
KL-EXD52E3		2003-2005	172
PJ-EXD52E6		2005-2006	100
KC-EXD52G2		1998-2000	4
KL-EXD52G3		2003-2005	31
PJ-EXD52G6		2005-2006	31
KC-EXD81D2		1997-1999	2
KC-EXD82D2		1997-2000	94
KC-EXD82E2		1997-2000	6
KC-EXD82G2	1997-2000	2	
		TOTAL	3,103