VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1874	DATE	October 18, 2012
MANUFACTURE	Automobiles PEUGEOT		
	(Japanese Importer :	PEUGEOT CITROËN JAI	PON Co.,Ltd.)
DESCRIPTION OF DEFECT	On the brake switch wiring harness surrounding brake link rod, wiring harness could cause it to come into contact with the surrounding components. In the long-term, ABS does not operate with ABS warning light turns on by the wiring harness damage. If wiring harness short-circuiting, the brake lamp does not lit on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A75F01	PEUGEOT 207		48
ABA-A7C5F01	PEUGEOT 207CC	2012	71
ABA-A7W5F01	PEUGEOT 207SW		140
		TOTAL	259