

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1873	DATE	October 18, 2012
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the components of the clutch master cylinder pipe in the power train, the clutch master cylinder pipe may cause clutch fluid to leak that crimping not properly on the linking-union between flexible pipe and hose end. It may occur the diagnostic warning light coming on and the risk that they are not changing gear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T75FX	PEUGEOT 308	2009	24
ABA-T75FY	PEUGEOT 308		1
		TOTAL	25