

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 0 2 8	DATE	Oct.4.2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to in inappropriate manufacturing the edge of the metallic harness cover under the driver' s seat, the main harness could be damaged by the edge in fitting the harness cover. If the vehicle continues to be driven in this condition, the harness may interfere with the cover and can cause a short circuit. In an extreme case, the reverse lamp could not turned on, or the engine may stall and can not be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-VR2E26	NV 3 5 0 CARAVAN	2 0 1 2	2, 643
LDF-VW2E26			805
LDF-VW6E26			492
CBF-CS4E26			37
LDF-CW4E26			35
LDF-CW8E26			14
CBA-KS2E26			116
CBA-KS4E26			10
		TOTAL	4, 152