VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No.

MANUFACTURE

DESCRIPTION OF

DEFECT

GAI-1869

may occur.

Automobili Lamborghini SpA

Domestic (Import) Vehicles DATE Oct 2, 2012 (Japanese Importer : Audi Japan) Since the material of the high pressure pipe used for the power steering unit is not appropriate, it may cause corrosion due to water when the pipe is used for a long time, and the high pressure pipe may have a small hole. This can result in leak of the power steering oil and

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-JFGE11	Gallardo	2004-2005	207
GH-JFGE12	Gallardo Gallardo Spyder	2006	82
		TOTAL	289

in low performance of the power steering. If the location of oil leak is close to a high temperature part such as engine exhaust pipe, oil on a high temperature part may cause smoke. In the worst case, a fire