VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 Gai-1889
 DATE
 2012/12/20

 MANUFACTURE
 Daimler AG
 (Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)
)

 DESCRIPTION OF DEFECT
 Since the bolts of the striker for the secondary catch hook of the engine hood were possibly screwed with an insufficient tightening torque, the striker might be loose. If the striker is loose and the primary locks are released due to some reasons, the safety function while driving might no longer be guaranteed.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
RBA-218359C	CLS350	2012	1
		TOTAL	1