

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-1885	DATE	Dec. 20, 2012
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>Transmission Range Sensor Replacement – Vehicles equipped with 6R80 Automatic Transmission – 2012 model Mustang                  Certain 2012 Mustang vehicles built at the Flatrock Assembly Plant from October 17, 2011 through January 9 2012.</p> <p>It may be possible that when the transmission gearshift lever is placed in reverse, the electronic transmission PRNDL display (if equipped) may not indicate “R” (reverse) and the back-up lamps may not operate. Additional symptoms that may be experienced intermittently include the vehicle does not move when reverse gear is selected and inoperative rear video camera.</p> <p>Dealers are to replace the transmission lead frame. All identified vehicles in APA Region require the transmission lead frame replacement.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	Ford Mustang, V6 Coupe	2012	1 unit
UNKNOWN	Ford Mustang, V8 Convertible	2012	1 unit
		TOTAL	2 units