

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 0 6 8	DATE	Dec.6.2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	The terminals of the connector on a bulb holder of the rear combination lamp might be deformed. Consequently, electrical insulating substances could be made between the terminals of the bulb holder and the wiring harness of body side, and the current could not flow correctly. Therefore, the lamp may not turn on, or the lamp may operate incorrectly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-AK12 CBA-AK12 DBA-AK12	MARCH	2 0 0 2 ~ 2 0 0 9	396,063
UA-BNK12 CBA-BNK12 DBA-BNK12			40,064
UA-BK12 CBA-BK12			41,947
DBA-YK12			15,443
UA-K12			3,767
ABA-FHZK12			MICRA C+C
		TOTAL	498,793