

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1884	DATE	Dec 6, 2012
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	<p>With regard to heavy duty trucks, due to inappropriate internal configuration of the wirings of EGR differential pressure sensor, the contact of the wirings in the protective tube by the influence of vehicle vibration, etc. may cause abrasion of the coating of the wirings. If used continuously, the coating of the wirings may peel off, and in the worst case, breaking or short circuit of the sensor wirings may cause a lighting of engine warning lamp and EGR failure, which may cause an excess of the standardized limit of exhaust gas.</p> <p>EGR (Exhaust Gas Recirculation system) A system that circulates the exhaust gas in the combustion chamber to avoid a rise in the temperature of exhaust gas and suppress the generation of nitrogen oxide.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
- B2TDA1 -	FH	2010	9
-H2TDA1-	FH	2011	1
-H2TEA1-	FH	2011	3
LDG-H3RTF1	FH	2010 - 2011	12
LKG-H2TDA1	FH	2010 - 2011	122
LKG-H2TEA1	FH	2010 - 2011	48
QKG-H2TDA1	FH	2011	10
QKG-H2TEA1	FH	2011	5
Unspecified	FH	2010 - 2011	120
		TOTAL	330