

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3086	DATE	January 31, 2013
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Incorrect seal ring had been installed on the brake actuator for a period of time. In such case, brake fluid will be leaked into the brake actuator, brake warning lamp may be turned ON and breaking performance be come down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-HA35S	ALTO	2013	ABOUT 140
DBA-MF33S	MR WAGON	2013	ABOUT 50
DBA-HE22S	ALTO LAPIN	2013	ABOUT 370
DBA-MK21S	PALETTE	2013	ABOUT 50
DBA-MA15S	SOLIO	2013	ABOUT 40
DBA-HB35S	CAROL	2013	2
DBA-MG33S	MOCO	2013	ABOUT 780
DBA-ML21S	ROOX	2013	ABOUT 520
		TOTAL	ABOUT 1,950