

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3083	DATE	30 Jan, 2013
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p>A bearing in a fuel pump may be worn because of its insufficient durability. It may cause abnormal noise. If it is continuously used, engine power could be decreased, then the bearing could be broken, creating a functional failure of the fuel pump that may lead to engine stall and unable to start again in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-EJ800A	W800	2011~2012	3,351
		TOTAL	3,351