

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1902	DATE	January 30 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the electric vehicle, due to the inappropriate sealing grease may leak from the transmission input shaft, which transfers the driving torque of the electric motor. In such case, the loss of lubrication can cause wearing of the spline, which may lead to bad traction of the electric motor and transmission, and in worst case it is not possible to move the vehicle on its own.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-UC20-	BMW ActiveE	2012	5
		TOTAL	5