

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3085	DATE	Jan. 25, 2013
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>During the assembling process, wrong sealing part was installed to some brake actuators.</p> <p>With this condition, brake fluid leaks into brake actuator through the sealing and warning indicator lights up. If using continuously, braking force may drop down in the worst case</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA100S	MOVE	2013	148
DBA-LA110S			13
DBA-LA100F	STELLA		5
DBA-LA110F			1
		TOTAL	167