

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3077	DATE	Jan.16.2013
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the light bar on the subject patrol cars, due to the improper structure tightening the upper cover to the lower cover of the light bar, there is a possibility that the tightening portion(s) may have a crack caused by vehicle vibration or solar heat. If the vehicle is continuously operated in this condition, the tightening portions may break, which could result in the upper cover becoming detached.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRS200	CROWN PATROL CAR	2010-2012	208
DBA-GRS201		2010-2012	68
DBA-GRS202		2010-2012	534
		TOTAL	810