

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	3111	DATE	Feb-26-2013
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	In the wing body which equipped lower mounted steel handle on the rear door, there are some cases that the latching length between the catch on the door and the keeper on the body is insufficient, due to the inappropriate production work. Therefore, when if the vehicle is driven under the unlocked condition by key, the catch part may move to the opening direction by eg. the torsional behavior of the rear body by the running on the road, and in the worst case, there is possibility to release the latch, and open the door.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FV54JZ	「FUSO SUPER GREAT」	2010	1
BKG-FS54JZ		2010	3
KL-FS54JVZ		2010	1
LKG-FS54VZ		2010～2012	809
LKG-FS55VZ		2010～2011	30
LKG-FU54VY		2010	1
LKG-FU54VZ		2010～2012	378
LKG-FU55VZ		2009～2012	17
LKG-FV54VZ		2011～2012	2
LKG-FY54VY		2010～2011	3
PJ-FS54JVZ		2012	1
QKG-FS54VZ		2012	181
QKG-FS55VZ		2012	9
QKG-FU54VZ		2012	98
QKG-FU55VZ		2012	1
SKG-FK64F	「FUSO FIGHTER」	2011	1
TKG-FK61F		2012	1
QKG-CYJ77A	「GIGA」	2012	1
LKG-CG5ZA	「Quon」	2011～2012	2
QKG-CD5ZA		2012	1
QKG-CG5ZA		2012	2
		TOTAL	1543