VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3099	DATE	February 15. 2013
MANUFACTURER	MITSUBISHI AUTOMOTIVE LOGISTICS TECHNOLOGY Co., Ltd.		
DESCRIPTION OF DEFECT	On the part of fastening lower and upper cover of the special warning lamp attached to vehicles, stress concentration has occurred around the insert nut of the lower cover. (16 locations in total) External factors such as running vibration or solar radiation may lead to cracks. Continuous usage in this condition may damage the joints and, in the worst case, cause the upper cover to come off.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF VEHICLE
	NAME	RECALLED	
CBA-V93W	MITSUBISHI PAJERO	2011	1
Z21AXSJH9	MITSUBISHI COLT	2011	1
		TOTAL	2