

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3097	DATE	February 15. 2013
MANUFACTURER	U-BODY AND PAINTING Co., Ltd.		
DESCRIPTION OF DEFECT	<p>On the part of fastening lower and upper cover of the special warning lamp attached to vehicles, stress concentration has occurred around the insert nut of the lower cover. (16 locations in total)</p> <p>External factors such as running vibration or solar radiation may lead to cracks.</p> <p>Continuous usage in this condition may damage the joints and, in the worst case, cause the upper cover to come off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP55V	TOYOTA SUCCEED	2012	2
		TOTAL	2