## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3096	DATE	February 15. 2013
MANUFACTURER	KONO BODY MANUFACTUARING Co., Ltd.		
DESCRIPTION OF DEFECT	On the part of fastening lower and upper cover of the special warning lamp attached to vehicles, stress concentration has occurred around the insert nut of the lower cover. (16 locations in total) External factors such as running vibration or solar radiation may lead to cracks. Continuous usage in this condition may damage the joints and, in the worst case, cause the upper cover to come off.		

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER
	NAME	RECALLED	OF VEHICLE
DBA-CWEAW	MAZDA PREMACY	2011	1
LDA-KE2AW	MAZDA CX-5	2011	1
DAA-ZVW30	TOYOTA PRIUS	2011	1
		TOTAL	3