

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3093	DATE	February 15. 2013
MANUFACTURER	KONISHI BODY Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>On the part of fastening lower and upper cover of the special warning lamp attached to vehicles, stress concentration has occurred around the insert nut of the lower cover. (16 locations in total)</p> <p>External factors such as running vibration or solar radiation may lead to cracks.</p> <p>Continuous usage in this condition may damage the joints and, in the worst case, cause the upper cover to come off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBF-VY12	NISSAN AD	2011	8
DBA-NT31	NISSAN X-TRAIL	2012	1
DBA-ACA33	TOYOTA VANGUARD	2011	1
		TOTAL	10