

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3092	DATE	February 15. 2013
MANUFACTURER	KEISYO SYATAI Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>On the part of fastening lower and upper cover of the special warning lamp attached to vehicles, stress concentration has occurred around the insert nut of the lower cover. (16 locations in total)</p> <p>External factors such as running vibration or solar radiation may lead to cracks.</p> <p>Continuous usage in this condition may damage the joints and, in the worst case, cause the upper cover to come off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRT261	TOYOTA PREMIO	2011	6
DBA-ACA31W	TOYOTA RAV4	2012	1
DBA-DE3AS	MAZDA DEMIO	2012	4
ABF-SKP2V	MAZDA BONGO	2012	3
DBF-VY12	NISSAN AD	2010-2011	3
CBF-VRE25	NISSAN CARAVAN	2012	2
DBA-Y12	NISSAN WINGROAD	2012	2
LDA-DNT31	NISSAN X-TRAIL	2012	1
DBF-VM20	NISSAN NV200VANETTE	2010	1
ABA-DA64W	SUZUKI EVERY	2012	2
		TOTAL	25