

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3108	DATE	Feb. 13, 2013
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>During the manufacturing process of pump which supplies negative pressure to power-brake booster on electric vehicle, some vane inside the pumps have crack.</p> <p>If using the pump continuously with this condition, the vane may break, power-brake booster loses its function and breaking distance increases.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S321V-EV	HIJET	2012	5
		TOTAL	5