

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

CAMPAIGN No.	3090	DATE	Feb. 12 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty route buses with automatic transmission, cracks may occur at the soldered portions in the automatic transmission electronic control unit. This may increase shift shock, make the gear fixed to a certain gear and, in the worst case, make the engine being unable to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-MP35FK	「FUSO AERO STAR」	2010 ~ 2012	31
LKG-MP35FM		2010 ~ 2012	245
LKG-MP35FP		2010 ~ 2012	81
LKG-MP37FK		2010 ~ 2012	432
LKG-MP37FM		2010 ~ 2012	93
QKG-MP35FK		2012 ~ 2013	13
QKG-MP35FM		2012 ~ 2013	89
QKG-MP35FP		2012 ~ 2012	65
QKG-MP37FK		2012 ~ 2013	144
QKG-MP37FM		2012 ~ 2013	48
QDG-MP35FM	「SPACERUNNER A」	2012 ~ 2012	7
QDG-MP35FP		2012 ~ 2013	9
LKG-AP35FM		2010 ~ 2011	20
LKG-AP37FK		2010 ~ 2011	24
LKG-AP35FP		2010 ~ 2011	3
LKG-AP37FM		2010 ~ 2010	5
LKG-AP35FK		2011 ~ 2011	2
	TOTAL		1,311