

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3 1 2 4	DATE	Apr.4.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to inappropriate the recovery program when the engine revolution decrease suddenly, the recovery control cannot operate, when the engine revolution suddenly decrease with the vehicle drive on the low engine revolution, by the compressor of air-conditioner was broken. In an extreme case, the engine may stall during the low speed driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-KJ10	DUALIS	2007~2010	17,590
DBA-KNJ10			8,618
DBA-J10		2007	13,699
DBA-NJ10			11,162
		TOTAL	51,069