

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1918	DATE	Apr.11.2013
MANUFACTURER	NUMMI		
DESCRIPTION OF DEFECT	<p>Due to improper compaction process and/or improper moisture absorption prevention measure for propellant wafers, the density of propellant wafers could be low. These propellant wafers may have been assembled in the passenger air bag inflators. In the event of an air bag deployment with such propellant wafers, pressure within the inflator body may abnormally increase. As a result, the inflator body could rupture, possibly scattering, potentially causing a fire in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-ZZE136	[VOLTZ]	2002-2004	3,153
TA-ZZE137		2002-2004	1,095
UA-ZZE138		2002-2004	1,636
		TOTAL	5,884