

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	GAI-1919	DATE	April. 11. 2013
MANUFACTURER	HONDA OF AMERICA MFG., INC.		
DESCRIPTION OF DEFECT	In certain vehicles, the inflator for passenger's airbag may be incorporating gas generating propellant which was rendered less dense than required due to inadequacies in its molding process or due to inadequate moisture absorption preventive after molding. In the event of the airbag deployment, there can be an abnormal increase in internal pressure of such an inflator, and the container of inflator could be thereby broken and scattered about, catching fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UN-EN2	「CIVIC_GX」	2001	102
		2002	106
		2003	51
		TOTAL	259