

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3137	DATE	Apr.11.2013
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>#1 On the rear access door, due to insufficient strength of the front seat belt retractor mounting portion, if the access door is repeatedly and forcefully closed over an extended period of time, the mounting portion may fracture, causing the seat belt to not work properly. In the worst case, the seat belt retractor may become detached and the seat belt could not be used.</p> <p>#2 In after market accessory covers, if they are installed in the lamps or seat belts, the vehicle may not comply with requirements prescribed in certain safety standard in Japan.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
CBA-GSJ15W	[FJ CRUISER]	2010-2013	12,183	#1 12,183 #2 189
TOTAL				12,183