VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 1 3 9	DATE	Apr.11.2013
MANUFACTURER	NISSAN		
DESCRIPTION OF DEFECT	The forming process step of the propellant of the propellant was due to inappropriate so of the propellant was propellant was front passenger air that are required to incorrect propellant was installed in certain pressure of the inflat deployment. In certain and the metal fragments	waters could not be creening operation a afer. As a result ht be included amore on a inflator contain operation operation operation deploy rafers with insufficition to rise excession cases, the inflators.	te. In addition, the completely screened to the forming process, certain incorrecting the products. The ms propellant wafers the air bag. Some itent density might be a cause the internal ively during air bag a housing may rupture

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
TA-AZ10	NISSAN CUBE	2000~2002	49, 691
TA-ANZ10			6, 405
TA-NT30	NISSAN X-TRAIL		23, 334
TA-T30			2, 424
GH-PNT30			1, 947
TA-RM12 UA-RM12	NISSAN LIBERTY	2001~2003	21, 497
TA-RNM12 UA-RNM12			3, 206
UA-QG10	NISSAN BLUEBIRD SYLPHY		9, 642
TA-QNG10			1,030
TA-FG10 UA-FG10			3, 624
GH-TG10			1, 113

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-A33 GH-A33	NISSAN CEFIRO	2 0 0 1 ~ 2 0 0 2	9, 163
GF-PA33			2, 182
UA-J31	NISSAN TEANA	2003	490
UA-PJ31			35
UA-TNJ31			25
TA-QGE25	NISSAN	2001~2004	178
GE-VPE25 LC-VPE25	CARAVAN		229
KG-VWE25			144
KG-VWME25			197
GE-CQGE25			99
KG-CWGE25			49
KG-CWMGE25			84
GE-DQGE25			134
KG-DWGE25			29
KG-DWMGE25			122
TA-WFGY61	NISSAN SAFARI	2002~2003	19
GF-WGY61			9
KH-WTY61			12
KG-VRGY61			13
GC-LFMD22	NISSAN	2 0 0 2	1
GC-LFD22	DATSUN		1
TA-JQGE25	I SUZU	2 0 0 1 ~ 2 0 0 2	1
GE-JVPE25 LC-JVPE25	COMO		7
KG-JVWE25		_	9
KG-JVWME25			16
GE-JCQGE25			3

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
KG-JCWGE25	ISUZU	2001~2002	3
KG-JCWMGE25	СОМО		10
GE-JDQGE25			3
KG-JDWMGE25			5
		TOTAL	137, 185