

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3142	DATE	April 11, 2013
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	In the inflator for passenger seat air bag, due to inappropriate molding process and/or handling to prevent moisture absorption of the inflator after molding, the propellant with insufficient density may be installed. Therefore, the inner pressure of the inflator may abnormally rise at the time of air bag deployment, and it may potentially cause a rupture and flying apart of inflator case, or result in catching fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-SE3P	Mazda 「RX-8」	2003	27
LA-GG3P UA-GG3P	Mazda 「ATENZA」	2002-2003	646
LA-GG3S UA-GG3S		2002-2003	1,522
LA-GY3W UA-GY3W		2002-2003	1,100
LA-GGEP UA-GGEP		2002-2003	533
LA-GGES UA-GGES		2002-2003	338
LA-GYEW UA-GYEW		2002-2003	218
		Total	4,384