

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3144	DATE	Apr. 18 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty double-decker buses, the waterproof quality of the connector for air conditioning unit harness is insufficient. In winter, salty water from snow-melting agent, etc. splashed over by the rear wheels may penetrate into the connector. If the water penetration and drying are repeated, the short-circuit in the connector or arcing around the connector may occur. This will burn the connector or harness and, in the worst case, resulting in fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
P-MU515TA	「FUSO AERO KING」	1984 ~ 1990	35
U-MU525TA		1991 ~ 1994	58
KC-MU612TA		1996 ~ 2000	28
MU612TX		2000 ~ 2005	133
BKG-MU66JS		2008 ~ 2010	44
		TOTAL	298