

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3147	DATE	April 19 ,2013
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		As for the fuel tank of a medium-size fire engine, water may accumulate on the fuel tank's bracket and remain there due to an improper bracket structure, resulting in rust at the lower end of the bracket. Note that continuous use under this condition may damage the lower end of the bracket, and in extreme cases, could cause the fuel tank to drop off	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FSR33D4	FORWARD	2000 - 2001	10
		TOTAL	10