

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3148	DATE	April 25, 2013
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>The engine of heavy duty trucks, sealing function of the butterfly shaft of the intake throttle valve for EGR control is inappropriate. That causes some condensation of water intake air from entering inside the intake throttle valve. Therefore, by continuing the use of the vehicle, condensation is transmitted to the wiring of the intake throttle valve and entering the engine control unit therein. Exhaust gas purifying process by EGR control may not work. Since the water comes into engine control unit, it doesn't work and DPF can't start manually. In the worst case, vehicle is running and makes an engine stall and might not be able to restart it.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CD5YA QKG-CD5YA	Quon	2012	30
LDG-CD5YL QDG-CD5YL QKG-CD5YL	Quon	2012	35
LDG-CD5ZA QKG-CD5ZA	Quon	2012	317
LDG-CD5ZL QKG-CD5ZL	Quon	2012	42
LDG-CF5XL	Quon	2012	35
LDG-CV5XL QKG-CV5XL	Quon	2012	5
LDG-CV5YL	Quon	2012	29
LDG-CW5XL QKG-CW5XL	Quon	2012	312
LDG-CW5YL QKG-CW5YL	Quon	2012	135
LDG-CX5YA QKG-CX5YA	Quon	2012	17
LDG-CX5YL QKG-CX5YL	Quon	2012	6
LDG-CZ5YL	Quon	2012	49
QKG-CD5XL	Quon	2012	2
QKG-CD5XM	Quon	2012	11
QKG-CD5ZE	Quon	2012	27

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CG5YA	Quon	2012	5
QKG-CG5YE	Quon	2012	3
QKG-CG5YL	Quon	2012	1
QKG-CG5ZA	Quon	2012	473
QKG-CG5ZE	Quon	2012	38
QKG-CG5ZL	Quon	2012	24
QKG-CG5ZM	Quon	2012	5
QKG-CK5XL	Quon	2012	7
QKG-CV5XA	Quon	2012	13
QKG-CV5YB	Quon	2012	11
QKG-CW5ZA	Quon	2012	37
QKG-CW5ZL	Quon	2012	59
QKG-GK5XAB QKG-GK5XAD QKG-GK5XAE	Quon	2012	253
QKG-GK6XAB QKG-GK6XAD QKG-GK6XAE	Quon	2012	187
LDG-HF5XL	—	2012	1
LDG-HZ5YL QDG-HZ5YL	—	2012	12
LDG-SF5XL	—	2012	2
LDG-SZ5YL	—	2012	12
		TOTAL	2,195