

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -1911	DATE	April 30, 2013
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a temporary screw connection assembly problem, existing threaded connections on the camshaft controller can become strained to such an extent that the function of the camshaft controller cannot be guaranteed over the service life of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-970M46	「Panamera」	2011	72
	「Panamera 4」	2011	47
ABA-970M46A	「Panamera」	2011	2
	「Panamera 4」	2011	1
ABA-970M48A	「Panamera S」	2010	13
	「Panamera 4S」	2010	38
	「Panamera Turbo」	2010	14
ABA-92AM48	「Cayenne S」	2011	85
ABA-92AM48A	「Cayenne Turbo」	2011	68
		TOTAL	340